

**LOTS OF  
LOOSE  
STITCHING**






OVERHEAD MESH IS A TERRIBLE DESIGN, HOOKS ARE CHEAP/CRAPPY, STUFF FALLS RIGHT OUT IF WINDY OR HOUSE IS JOSTLED TOO MUCH (SEPARATE VIDEO)







OUTSIDE DOOR FLAP - VELCRO DOESNT LINE UP



WINDOW COVERS LOOSE - CANT BLOCK OUT LIGHT



REMOVABLE WINDOWS SIZE HAS POOR TOLERANCE - END UP WITH OVERHANG OR "BUBBLE" AT EDGES - HARD TO LINE UP WITH VELCRO



POSITION THE VELCRO IS SUPPOSED TO BE (LOWER CORNER WINDOWS)



VELCRO ONLY HAS HALF OVERLAP AT BEST WHEN PULLING WINDOW FLAPS TIGHT



POCKET MATERIAL VERY STIFF -  
VERY LITTLE ROOM TO PUT STUFF  
IN, HARD TO GET STUFF OUT

MaxiFlex®  
CE U1000614-1  
2012 24-034  
10(XL)  
GATE  
Sungard  
Patent No. EP 1 608 808  
www.stg-gm-solutions.com